

Marked drawing Submitted with 1st amendment & response
for application 10/699,272.




FIG. 5




FIG. 6

Tapering towards elongated opening




FIG. 7




FIG. 8

In this side view, shroud 57 is seen tapered in only one direction towards wrench head 43.




FIG. 9

In this top view, shroud 57 is seen tapered in only one direction towards wrench head 49.




FIG. 10

This is because the tapering at one end of shroud 57 is perpendicular to the tapering at the other end thereof.